

Site Name	Feature Location	6 D's	Reasons	Existing species	Planting notes	Replant species
MILLTHORPE ROAD	opp 1 Millthorpe Rd	TR: Felling	Kerbs displaced by buttress root, unable to work round	Fraviniis Avcalsior	Liquidambar	Plant in verge in same position OPPOSITE 1 Millthorpe Rd (1st 1 of 2 in this verge)
MILLTHORPE ROAD	OPPOSITE 1 Millthorpe Rd	TR: Felling	C/W uplifted by shallow rooting, kerbs displaced also	Platanus x hispanica	Liquidambar styraciflua 'Worpl	Plant in verge in same position OPPOSITE 1 Millthorpe Rd (2nd 1 of 2 in this verge)
MILLTHORPE ROAD	Adj 1 , Just below top of Rd, junct with Willington Rd	TR: Felling	F/W uplifted	Platanus x hispanica	Istyraciflua 'Wornl	Plant in verge in same position outside 1 Millthorpe Rd